

FOTECOAT 1860

Presensitized, polymer, solvent resistant, ready-to-coat screen emulsion

1. DESCRIPTION

- ♦ Fast, presensitized emulsion ready-to-coat; free of Diazo
- ♦ Completely solvent resistant and very easy to decoat
- ♦ Available in green or purple color with high contrast
- ♦ Solids content 35%; high viscosity
- ♦ Economic to use
- ♦ Harmless for sewage and at the working place

2. APPLICATION ADVANTAGES

- ♦ No mixing; does not need degassing: therefore less pinholes
- ♦ Best printing results are reached on dyed polyester and on steel mesh
- ♦ Good resolution and stencil edge sharpness
- ♦ Can be easily removed with the usual products
- ♦ Thanks to the mat stencil surface static problems can be avoided

3. MANUAL AND MACHINE COATING

- ♦ Manual: The ready-to-coat emulsion can be used by the 2/3 technique. Because of the high viscosity of this emulsion the same technique can be used for coarse mesh
- ♦ The viscosity is ideal for coating machines. If necessary the emulsion can be thinned with water without losing light sensitivity
- ♦ To produce a flatter stencil profile and a lower Rz-value - to improve the print edge sharpness - additional coatings are possible after intermediate drying. The stencil thickness increases by 1-2 microns and the Rz-value is lowered with each additional coat onto the dried surface
- ♦ If the emulsion is poured back into the can after coating, it will be necessary to check before the next coating if the emulsion is degassed completely; check if there are no longer air bubbles on the emulsion surface. The reason is, that like all screen emulsions, air is sucked into the emulsion during stirring or coating. Such air bubbles are the main cause for pinholes

4. STENCIL QUALITY

Thanks to high solids content and the perfect viscosity an excellent mesh bridging is reached. The edge definition is reasonably good. Coupled with high resolution characteristics and the short exposure time excellent stencils on both dyed and white mesh or on steel mesh can be produced if an adequate coating technique is used. On white polyester the definition is somewhat lower and the exposure latitude decreases.



FOTECO

info.fotec@saati.com

FOTECOAT 1860

Presensitized, polymer, solvent resistant, ready-to-coat screen emulsion

5. STORING

This ready-to-coat emulsion should be stored in a closed can, protected from direct a light. Protect also against freezing.

Condition	Service Life
Unsensitized, 18-25°C storage	2 years
Pre-coated screens in total darkness at 20°C	4 weeks
Coated, packed in black plastic, 20°C, 50-70% relative humidity	6 months

6. EXPOSURE TIMES

- ◆ Light sources with a spectral light output between 320 - 380 nm can be used
- ◆ Metal halogen lamps with a photopolymer bulb are ideal for FOTECOAT 1860
- ◆ The loss on UV-light during the working time of the lamp must be considered (approximately 10% per 100 burning hours)
- ◆ This emulsion has a high light sensitivity. The exposure latitude is therefore re-duced. This needs a careful step wedge to find the optimum result in respect of ex-posure time. Longer exposure produces better mechanical resistance of the stencil but shows losses in the resolution
- ◆ Exposure time with a 5 kW MH-lamp, gallium-iron charged burner, at 100 cm distance on yellow mesh 120T-34 and 14 microns stencil build-up is approximately 40 seconds. (Coating 2x printing side, 3x squeegee side, wet in wet.)
- ◆ White mesh causes a stronger undercutting of the light. On 120T-34 white at 14 microns stencil thickness approximately 20 seconds exposure time are needed
- ◆ If fluorescent tubes are used we recommend only super actinic (solarium) tubes
- ◆ The Philips HPR-125 W lamp is an adequate light source if the stencil is covered during the 4 minutes warm-up time of the lamp

7. STENCIL REMOVAL

- ◆ The old rule is valid: The better the hardening of the stencil system through a longer exposure time, the easier the stencil removal
- ◆ This screen emulsion is free of Diazo. Therefore no brownish residues on the mesh; the removal of ghost images is simplified
- ◆ The stencil removal is simplified if the ink is removed immediately after printing. Then firstly degreasing with FOTECHEM 2003 ready-to-use or FOTECHEM 2033 Concentrate, diluted 1:10, is recommended
- ◆ FOTECHEM 2004 liquid; FOTECHEM 2005 paste
- ◆ FOTECHEM 2042 concentrated liquid decoater (1:30) for machine decoating
- ◆ FOTECHEM 2048 is a more efficient liquid concentrate (1:30) for decoating
- ◆ FOTECHEM 2044 powder
- ◆ The stencil removal is simple and fast without high pressure gun
- ◆ Ghost images: Brush on FOTECHEM 2085 (a blend of emulsifying solvents), then apply FOTECHEM 2080 (high alkaline paste) with a brush; let stand for maximum 1hour, then hose off with mild spray before the residues are jetted off with a high power spray. Do not let dry on the mesh. Or use FOTECHEM 2089 (one component) and apply by coating trough.

SAATI S.p.A.

These Technical Informations are published without warranty. The results shown in these Technical Informations are based on laboratory testing. The supplier declines any responsibility for incorrect use of these products which are manufactured and sold for industrial use only.

info.fotec@saati.com